

SERVICE REPORT

Job Number:	IN1346	Quote: -----	Sage: -----
Customer:	Natural Resources Institute Finland (LUKE)		
Contact:	Elina Sahlstedt (00358504324879)		
Instrument:	HS2022 Emag		
Date of Visit:	14-15.5.2026	Days:	2
Engineer:	Robert Kameny		
Reason for Visit:			
Service Visit			
Service Contract?	Yes / No	Expires:	N/A
Warranty?	Yes / No	Expires:	30.1.2027
Tick as Applicable:	☒ Call Out / ☒ Routine Service / ☐ Warranty / ☐ Emergency / ☐ Contract Visit		
Details of Visit:			
- Customer reported severe issues with 18O results during LA analysis for last 6 months - Symptoms: noticeable oscillations across all 3 beams during stability scans, regular spike pattern spiced apart every 2 minutes or so, - Attempts to fix since first report (Henry Cook visit 04_2026): Replaced Analyser Turbo pump (05/2026), swapped system controller, head amp cable, source cable, re-plumbed REF side, replaced LA prep isolation valve - Recommended actions: head Amp replacement, Emag/ Emag supply replacement - RK to visit site 05_2026 - Observed identical issues as listed above - Suspected areas: - Mass spec has tendency to be slower getting background down when running samples of the LA, causing the peaks to tail off (possible carry over) - Ref gas specs using CO gives good reproducible carbon and oxygen results - Att. Marginal/ poor stability trace observed at the start of the troubleshooting for N2 mode (Mass 30 has tendency to incline across time), CO2 and CO 2/1 and 3/1 scans also highlight noticeable instability over the time. - Attempts to fix : Head Amp replaced (no improvement), Replaced 24V solenoid control valve V4 (ref gas side) to mitigate any potential malfunction (no improvement), Re-placed 6 thou feed link(and re-crimped to 4.0e-06mBAR) on the LA isolation valve – (no improvement), Increased the E-mag Drive current to match 14000Amps (Att. unable to set the drive current higher than 13950Amps) made very little or no effect at the re-occurring oscillations			

SERVICE REPORT

Recommendations:

- Consider : Magnet/ Magnet power supply exchange
- Consider : Turbo Pump replacement (source)
- Consider : Sending the Mass Spec to Sercon for a detailed testing

Follow Up:

<i>Parts Used:</i>	<i>Stock Number:</i>	<i>Quantity:</i>	<i>Charge:</i>
Total:			

Engineer: Robert Kameny

Date: 21.05.2026

Signed:



Customer: Elina Sahlstedt

Date: 21.5.2026

Signed:



SERVICE REPORT

SERVICE REPORT

NOTES: